

MATERIAL SAFETY DATA SHEET

MICROFIBER CLEANING CLOTH

Page 1 of 1

Date of Issue: DEC. 07, 2016

SECTION 1. PRODUCT AND COMPANY IDENTIFICATION

Company: PHOTODON
Address: 2682 Garfield Rd N, Ste 21, Traverse City, MI 49686
Telephone Number: 847-377-1185
Fax Number: 877-255-2570
Web Page: <https://www.photodon.com>
E-Mail Address: sales@photodon.com
Product Name: Microfiber suede, (TR7054)
Common Name: Microfiber cleaning cloth (TR7054)

SECTION 2. COMPOSITION / INFORMATION ON INGREDIENTS

	Proportion
Ingredients	80% polyester , 20% nylon(poliamide)

SECTION 3. HAZARDS IDENTIFICATION

Emergency Overview : No hazards to incidental or prolonged exposure

Potential Health Effects

Inhalation: Not expected to be a health hazard from inhalation
Ingestion: Not expected to be a health hazard via ingestion.
Skin Contact: Not expected to be a health hazard from skin exposure.
Eye Contact: Not expected to be a health hazard from eye exposure.
Effects of Chronic Exposure : No information found.
Medical Conditions Aggravated: No information found.

SECTION 4. FIRST AID MEASURES

Inhalation:
Not expected to require first aid measure.
Ingestion:
Not expected to require first aid measure.